Run II LU Organizational Chart by WBS March 10, 2006 Run II Luminosity Upgrades Jeff Sims, Project Manager Mike Martens, Technical Lead 1.0 2.0 **Luminosity Upgrades** Vulnerability/Reliability Imp. Jeff Sims Paul Czarapata 1.01 1.02 1.03 1.04 1.06 2.01 **Protons on Target** Pbar Acceptance Pbar Stacking and Cooling **Tevatron High Luminosity** Project Management Vulnerability Upgrades Loanis Kourbanis Steve Werkema Paul Derwent Ron Moore Jeff Sims Paul Czarapata 1.01.01 1.02.01 1.03.01 1.04.01 2.02 Slip Stacking Li Lens S&C Task Force Beam Studies and Simulation Reliability Upgrades Valeri Lebedev Complete Jim Morgan Complete Paul Czarapata 1.01.02 1.02.02 1.03.02 1.04.02 Pbar Target & Sweeping AP2 and DB Acceptance Debuncher Cooling Active BBC Jim Morgan Keith Gollwitzer Vladmir Shiltsev Complete 1.01.03 1.03.03 1.04.03 Stacktail Upgrade MI Upgrades Inc. Helix Separation Loanis Kourbanis Paul Derwent Ron Moore 1.01.04 1.03.04 1.04.04 Booster MI Cogging Recycler Commissioning **Chromatic Compensation** Complete Complete Jerry Annala 1.01.05 1.03.05 1.04.05 OTR Electron Cooling Imp. Controls and Diag. Complete Complete Complete 1.01.06 1.03.06 1.04.06 Rapid transfers Operational Improvements for Tev Vacuum Imp. Protons - Complete Paul Derwent Complete 1.03.07 1.04.07 Add. Recycler Upgrades **TEV Alignment** Paul Derwent Jim Volk 1.03.08 Add. Electron Cooling Upg. Paul Derwent 1.03.09 Pbar Stack Rate Task Force Dave McGinnis